Nordhydraulic
HYDAC INTERNATIONAL

**Working title:**
**Valve type: RM271** **Valve specification: RM 270** **Status: Manufacture**
Made by: Jan Ekström Updated: 2011-06-17 Date of reg:2010-10-04

**Customer Part No: Amab+std**
**Part No:1601-006310**
Print date:2019-03-21

| Monobl.valve | AA00 | Body | BN00 | Main relief valve | BN04 | Check valve B-side | AA20 | El.contr.v. |
|---|---|---|---|---|---|---|---|---|
| | | **RM271A**<br>2005-6910092 | | **TBD200-260**<br>2275-200246 | | **MB01**<br>2250-220017 | | **PE50**<br>2310-6919227 |

| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| BH | Spool | **107AA1**<br>2125-3905331 | | | | | | | | | |
| | Function | | | | | | | | | | |
| BS | Instr. assembly | | | | | | | | | | |
| CE | Service port valve A-side | **P204**<br>2310-3900371 | | | | | | | | | |
| CP | Service port valve B-side | **P204**<br>2310-3900371 | | | | | | | | | |
| DB | Spool control A-side | **PMK2**<br>2175-804292 | | | | | | | | | |
| DM | Spool control B-side | **M19**<br>2200-269632 | | | | | | | | | |
| DY | Port A | | | | | | | | | | |
| EJ | Port B | | | | | | | | | | |

**Part No:** **1601-006310**

| | | | | |
|---|---|---|---|---|
| **FF** | Pressure ports | **P1** | **P2** | **P3** |
| | | **PPG4**<br>8030-000041 | **PG06**<br>2310-450100 | |
| **FQ** | Tank ports | **T1** | **T2** | |
| | | **KS50G1**<br>8030-000074 | **PG06**<br>2310-450100 | |
| **FV** | Instr. testing | | | |
| **FY** | Instr. testing | **PHAPG**<br>8052-296059 | | |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **Remain.spec.** | **GC04** | **Connecting manifold 1** | **GC09** | **Miscellaneous** | **GC12** | **Instruction marking** | **BS** | **Instr. assembly** |
| | | | | | | | | |
| | **GC13** | **Type Plate** | **GC16** | **Instruction packing** | **GC20** | **Instruction painting** | **GC28** | **Customer No** |
| | | | | | | | | |


BN04
CE
DB
AA00
BN00
AA20
DY
T1
FQ
T2
FQ
P1
FF
P2
1
2
3
4
T2
T1
A
B
P3
FF
P2
FF
EJ
DM
BH
CP